

Fig.1 Posizionare spine (P), barilotti(S),tiranti(U) nei fianchi(B e C)
 Fig.1 Position the pins (P), barrels (S) and tie-rods (U) in the sides (B and C)

1) Posizionare le spine (P), i barilotti (S), i tiranti (U) e piedini (Q) nei fianchi (B e C).
 1) Position the pins (P), barrels (S), tie-rods (U) and feet (Q) in the sides (B and C)

2) Posizionare i barilotti (T) nella traversa (D).
 2) Position the barrels (T) in the cross panel (D)






Fig.2 Posizionare spine (P) e tiranti(U) nel piano (A)
 Fig.2 Position the pins (P) and tie-rods (U) in the top (A)

3) Posizionare le spine (P), e i tiranti(U) nel piano (A).
 3) Position the pins (P) and tie-rods (U) in the top (A)

4) Unire i fianchi (B e C) alla traversa (D) tramite le spine (P) e i tiranti (U)
 4) Unite the sides (B and C) to the cross panel (D) by means of the pins (P) and tie-rods(U)








Fig.1 Serraggio grani (V e R) nei barilotti (T e S)
Fig.1 Tighten the treaded screws (V and R) in the barrels (T and S)



5) Serraggio grani (V e R) nei barilotti(T e S)
5) Tighten the treaded screws (V and R) in the barrels (T and S)



6) Posizionare il Piano (A), sopra la struttura e agganciarlo tramite le spine (P) e i tiranti (U)
6) Position the top (A) on top of structure and fasten it by means of the pins (P) and tie-rods (U)





Fig.2 Serraggio grani (V e R) nei barilotti (T e S)
Fig.2 Tighten the treaded screws (V and R) in the barrels (T and S)



7) Serraggio grani (V e R) nei barilotti(T e S)
7) Tighten the treaded screws (V and R) in the barrels (T and S)

